

# Traversing Basics

- raw measures: SD (note chain is straight), slope (of chain), bearing
- Calculate: HD & DE (note loss of detail)
- mapping: Brg & HD (label with Elev → spot ht.) – discussed later

